December 6, 198%

TO: Minerals File

FROM: Holland Shepherd, Reclamation Soils Specialist

RE: Site Visit, Nephi Gypsum, M/023/011, Juab County, Utah

A brief stop was made at the Nephi Gypsum site on December 2, 1988. The stop was made to determine whether or not the berm protecting Salt Creek from surface drainage had been repaired.

The berm has been repaired, although snow cover at the site made it difficult to determine the extent of repair. The berm located next to the gravel quarry, is now intact. I was unable to determine whether the berm had been repaired at its eastern most extent, because of snow cover.

jb cc: L. Braxton W. Hedberg MN4/58